

LASER PEGS®

The Ultimate Toy For Kids®

870

For Boys And Girls
Ages 5 And Up

12 Models+
Any creation you can build

LIGHTED
CONSTRUCTION SET INCLUDES

• 20 Laser Pegs®
• 84 Construction Parts
• Triangle Power Base
• Instruction Manual

Requires 3 AA Batteries

Batteries NOT
Included



EN71, RoHS COMPLIANT




This product complies to
all safety requirements
of ASTM F 963

MODEL INSTRUCTIONS

All additional model instructions can
be downloaded at www.LaserPegs.com

Laser Peg® Parts List


There is No LED In The 90 Degree Peg




Each Laser Peg® is color coded on the circuit board inside
each shape. There is No LED In The 90 Degree Peg.



Laser Pegs® link that
allows you to connect to
other construction kits.




Triangle Power
Base



Laser Pegs®
Peg Cord


Construction Parts List



www.LaserPegs.com

This manual is copyright and cannot be reproduced or used online without Laser
Pegs® Ventures LLC permission. Copyright 2012 © All Rights Reserved US Patent
#7,731,558 Additional Global & Multiple Patents Pending. Laser Pegs® Ventures
LLC. 8304 Consumer Ct Sarasota FL. 34240. Contact: Support@LaserPegs.com


Connecting Pegs




To construct with Laser Pegs®, slide two pieces together to form a connection. Slide each piece on and off smoothly. To build away from the Triangle Power Base, use the peg cord in one of the top three peg holes to illuminate your model! The 90° Pegs are essential to construction but they DO NOT ILLUMINATE.

Press button to turn on/off

Push button to cycle
through 3 different
light settings.



Connect Laser Pegs® TRIANGLE POWER BASE




To build away from the Laser Pegs®
Triangle Power Base use the Peg
Cord in one of the top three holes to
illuminate your model!

When you remove a peg from another
peg or model DO NOT PULL ON CORD!

Replacing Batteries


1. Remove screws.
2. Place three AA batteries in the correct position - as displayed inside the Triangle Power Base.
3. Push RED button to turn on!
4. Do not mix old and new batteries.
5. Do not mix alkaline, standard (carbon-zinc), or rechargeable (nickel-cadmium, NiMH) batteries!
6. Exhausted batteries are to be removed from the power base.
7. Never connect more than 200 Laser Pegs®
8. Non-rechargeable batteries are not to be recharged.
9. Rechargeable batteries are only to be recharged under adult supervision.
10. Rechargeable batteries are to be removed from the toy before being recharged.
11. Batteries are to be inserted with the correct polarity.
12. The supply terminals are not to be short-circuited.



Remove the three Phillips head
screws with a 4mm screw driver.
Requires (3AA) Batteries

Using an AC Adapter

Remove all batteries
from Laser Pegs® Power
Base before using the
5-volt AC adapter.



When using an AC
Adapter, NEVER
place the adapter
plug into the Tri-
angle Power Base
top peg holes.

*To avoid short-circuits, keep metal objects and
other un-authorized materials from obstructing
the peg holes.

Never connect more than 200
Laser Pegs® when using a 5-volt
(2000mA) AC Adapter.

The AC adapter and the Triangle Power Base are to be regularly examined for
damage to the cord, plug, enclosure and other parts, and in the event of such
damage, they must not be used until the damage has been repaired.

WARNING! Each Laser Peg® draws current from the batteries. Therefore, the more
pegs you use, the quicker you will deplete your battery power! As the power
weakens, the current will slowly fail and some Laser Pegs® will illuminate (typically
the reds and yellows) and some won't. When the Laser Pegs® dim, the Laser Pegs®
are not broken, they just need stronger batteries or an AC Adapter.

You have 3 simple options...

1. Use a 5-volt AC Adapter - available from www.LaserPegs.com
2. Change the batteries.
3. Use high quality batteries. They will last a little longer, but they will still deplete rapidly the more laser pegs you connect!



INDY CAR — A high performance automobile built for racing at incredible speeds.



Indy Car

Model
Difficulty
Level

2



STEP
1




STEP
2




STEP
3




STEP
4




STEP
5




STEP
6




STEP
7




STEP
8





STEP
9




STEP
10




STEP
11




STEP
10




STEP
11




STEP
12




STEP
13




STEP
14




STEP
15




STEP
16




STEP
17




STEP
18

















STEP
19



STEP
20







STEP

49

COMBINE


A

D




STEP

50




MODEL INSTRUCTIONS


All additional model instructions can be downloaded at www.LaserPegs.com




MINI SPACE SHUTTLE




TRANSPORT SHUTTLE




T-I SUBMARINE




STARSHIP




2 STAGE ROCKET




MINI MONSTER TRUCK




OLD TIME TRACTOR




4 WHEELER



HOVER CRAFT



MARS
MINI BOT



V RACER

www.LaserPegs.com

Copyright 2012© All Rights Reserved Global & Multiple Patents Pending.
US Patent #7,731,558